


Over the last 10 years, 10 coal miners were fatally injured when they were caught between moving parts of roof bolting machines and other stationary objects.

An average of one coal miner every year.
One miner who won't be coming home after work;
One miner who won't be playing with his children;
One miner, who won't be with his family.



Don't let that one miner be you!

BEST PRACTICES

- Always be aware of your location in respect to the moving parts of the machine.
- Stay out of pinch points between moving machinery parts and other objects.
- Make sure the controls on the machine are in proper working order.
- Place materials where you don't have to reach across the drill boom or drill head.
- Store materials where machine movement will not cause them to contact the controls.

